

# H-53 WIRING SYSTEM AWARENESS


## PREVENTING WIRING SYSTEM FAILURE

SAVES TIME, MONEY...


AND LIVES!



Misrouted wiring.




Wiring outside of clamp wedge.



Damage to hydraulic line due to spiral wrap lying on it.

Wire routed over plastic tie strap.



Kapton wiring routed over plastic tie straps.

Chafed Kapton.

ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION!