


# E-2C WIRING SYSTEM AWARENESS

## PREVENTING WIRING SYSTEM FAILURE

SAVES TIME, MONEY...

AND LIVES!




Cut wires left attached.




Prop de-icing harness chafing corner of oil tank.



Properly stowed connectors, but need environmental protection (silicon tape) to prevent corrosion.



C-clamp loose. Misrouted "Battle Repair" wiring.



Chafing condition.

Worn clamp.

ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION!