


E-2C WIRING SYSTEM AWARENESS


PREVENTING WIRING SYSTEM FAILURE SAVES
TIME, MONEY...

AND LIVES!



Bottom left bundle chafing against power supply.

Cushion clamp rubber misaligned.



Solder ferrules too close to connector. This will not allow for any repairs and requires cannon plug/harness replacement.



Missing clamp allowing wiring to chafe against structure.

ALWAYS MAINTAIN THE CORRECT WIRING
SYSTEM CONFIGURATION !