


E-2C WIRING SYSTEM AWARENESS

PREVENTING WIRING SYSTEM FAILURE SAVES
TIME, MONEY...

AND LIVES!


Excessive bend radius.



Plastic clamp incorrectly installed and chafing.



Power wiring transitioning through armpit chafing structure.



Harnesses missing clamps at critical clamp marker point. Purple tape signifies critical clamp point.



Improper installation of zip ties causes chafing.

ALWAYS MAINTAIN THE CORRECT WIRING
SYSTEM CONFIGURATION!