


H-60 WIRING SYSTEM AWARENESS

PREVENTING WIRING SYSTEM FAILURE

SAVES TIME, MONEY...

AND LIVES!




Flight control tubes tied to wiring inducing stress.



Shielding deteriorated, no longer provides EMI protection to system.



Harness chafing against Flight Control hydraulic lines.



Worn tape at strain relief. Wire has two splices within inches of each other (should only have one splice).

ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION!