


H-46 WIRING SYSTEM AWARENESS

PREVENTING WIRING SYSTEM FAILURE SAVES TIME, MONEY...

AND LIVES!




Braided line chafing on structure.




Wires outside of clamp rubber wedge.



Harness chafing on hydraulic line.



Connector disconnect not properly stowed.



Broken/Uncapped wiring.

ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION !