

# H-46 WIRING SYSTEM AWARENESS


## PREVENTING WIRING SYSTEM FAILURE

SAVES TIME, MONEY...

AND LIVES!



Connectors not properly capped and stowed.




Ground wire broken or unused?



Improperly capped/stowed connectors. Plastic bags for short-term stowage ONLY.



Heater control valve cable damaging hydraulic line.



Coaxes should have been routed behind hydraulic lines.

ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION!