

OSHA Citations
 Serious Violations
 FY 2006

Installation	UIC	Open Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Max Private Sector Penalty
Naval Sea Logistics Center, Ft Greely Mission Defense, Delta Junction, AK 99737	66135	10/19/2005	Planned	Serious	1926.25(a)	Housekeeping. During the course of construction, alteration, or repairs, form and scrap lumber with protruding nails, and all other debris, shall be kept cleared from work areas, passageways, and stairs, in and around buildings or other structures.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/3/2006	\$7,000
Naval Sea Logistics Center, Ft Greely Mission Defense, Delta Junction, AK 99737	66135	10/19/2005	Planned	Serious	1926.25(b)	Housekeeping. Combustible scrap and debris shall be removed at regular intervals during the course of construction. Safe means shall be provided to facilitate such removal.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/3/2006	\$7,000
Naval Sea Logistics Center, Ft Greely Mission Defense, Delta Junction, AK 99737	66135	10/19/2005	Planned	Serious	1926.151(a)(3)	Fire prevention. Smoking shall be prohibited at or in the vicinity of operations which constitute a fire hazard, and shall be conspicuously posted: "No Smoking or Open Flame."	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/3/2005	\$7,000
Naval Sea Logistics Center, Ft Greely Mission Defense, Delta Junction, AK 99737	66135	10/19/2005	Planned	Serious	1926.152(c)(5)	Flammable & combustible liquids. Storage areas shall be kept free of weeds, debris, and other combustible material not necessary to the storage.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	12/2/2005	\$7,000

OSHA Citations
 Serious Violations
 FY 2006

Naval Sea Logistics Center, Ft Greely Mission Defense, Delta Junction, AK 99737	66135	10/19/2005	Planned	Serious	1926.252(e)	Disposal of waste materials. All solvent waste, oily rags, and flammable liquids shall be kept in fire resistant covered containers until removed from worksite.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	12/2/2005	\$7,000
Naval Sea Logistics Center, Ft Greely Missile Defense, Delta Junction, AK 99737	66135	10/19/2005	Planned	Serious	1926.300(b)(5)	Guarding. When the periphery of the blades of a fan are less than 7 feet (2.128 m) above the floor or working level, the blades shall be guarded. The guard shall have openings no larger than 1/2 inch (1.27 cm).	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/3/2006	\$7,000
Naval Base Ventura County, Port Hueneme, CA 93041	69232	10/31/2005	Planned	Serious	1910.37(a)(3)	Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. The exit access must not go through a room that can be locked, such as a bathroom, to reach an exit or exit discharge, nor may it lead into a dead-end corridor. Stairs or a ramp must be provided where the exit route is not substantially level.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/15/2006	\$7,000
Naval Base Ventura County, Port Hueneme, CA 93041	69232	10/31/2005	Planned	Serious	1910.253(b)(2)(iv)	Welding, cutting & brazing: Valve protection caps, where the cylinder is designed to accept a cap, shall always be in place, hand-tight, except when cylinders are in use or connected for use.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/15/2006	\$7,000

OSHA Citations
Serious Violations
FY 2006

Naval Base Ventura County, Port Hueneme, CA 93041	69232	10/31/2005	Planned	Serious	1910.253(b)(4)(iii)	Oxygen cylinders in storage shall be separated from fuel-gas cylinders or combustible materials (especially oil or grease), a minimum distance of 20 feet (6.1 m) or by a noncombustible barrier at least 5 feet (1.5 m) high having a fire-resistance rating of at least one-half hour.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/14/2006	\$7,000
Naval Base Ventura County, Port Hueneme, CA 93041	69232	10/31/2005	Planned	Serious	1960.8(a)	Agency responsibility. The head of each agency shall furnish to each employee a place of employment which is free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	1/19/2006	\$7,000
NSWC Indian Head Division, 800 Seal Beach Blvd, Seal Beach, CA 90740	61065	2/16/2006	Unplanned Fatality Investigation	Serious	1960.8(a)	Agency responsibility. The head of each agency shall furnish to each employee a place of employment which is free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/30/2006	\$7,000
NSWC Indian Head Division, 800 Seal Beach Blvd, Seal Beach, CA 90740	61065	2/16/2006	Unplanned Fatality Investigation	Serious	1960.8(a)	Agency responsibility. The head of each agency shall furnish to each employee a place of employment which is free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/30/2006	\$7,000

OSHA Citations
Serious Violations
FY 2006

NSWC Indian Head Division, 800 Seal Beach Blvd, Seal Beach, CA 90740	61065	2/16/2006	Unplanned Fatality Investigation	Serious	1960.8(a)	Agency responsibility. The head of each agency shall furnish to each employee a place of employment which is free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/30/2006	\$7,000
NSWC Indian Head Division, 800 Seal Beach Blvd, Seal Beach, CA 90740	61065	2/16/2006	Fatality Investigation	Serious	1960.8(a)	Agency responsibility. The head of each agency shall furnish to each employee a place of employment which is free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/30/2006	\$7,000
Naval Exchange Maintenance SHO Bldg 151, Naval Base Guam, Santa Rita, Guam 96915	61755	3/14/2006	Planned	Serious	1910.36(d)(1)	Exits. Employees must be able to open an exit route door from the inside at all times without keys, tools, or special knowledge. A device such as a panic bar that locks only from the outside is permitted on exit discharge doors.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	5/22/2006	\$7,000
Naval Exchange Maintenance SHO Bldg 151, Naval Base Guam, Santa Rita, Guam 96915	61755	3/14/2006	Planned	Serious	1910.213(g)(3)	Woodworking machines. Limit chains or other equally effective devices shall be provided to prevent the saw from swinging beyond the front or back edges of the table, or beyond a forward position where the gullets of the lowest saw teeth will rise above the table top.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	5/31/2006	\$7,000

OSHA Citations
 Serious Violations
 FY 2006

DECA Central Distribution Agency, Bldg 3201, Naval Base Guam 96915	61755	3/17/2006	Planned	Serious	1910.37(a)(3)	Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. The exit access must not go through a room that can be locked, such as a bathroom, to reach an exit or exit discharge, nor may it lead into a dead-end corridor. Stairs or a ramp must be provided where the exit route is not substantially level.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/12/2006	\$7,000
DECA Central Distribution Agency, Bldg 3201, Naval Base Guam 96915	61755	3/17/2006	Planned	Serious	1960.8(a)	Agency responsibility. The head of each agency shall furnish to each employee a place of employment which is free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	5/22/2006	\$7,000
NCTAMSLANT Det 175 Ridge Road Cutler, ME 04626	None	3/17/2006	Unplanned-complaint	Serious	1910.120(q)(2)	Elements of an emergency response plan. The employer shall develop an emergency response plan for emergencies which shall address, as a minimum, the following areas to the extent that they are not addressed in any specific program required in this paragraph.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	11/17/2006	\$7,000

OSHA Citations
 Serious Violations
 FY 2006

NCTAMSLANT Det 175 Ridge Road Cutler, ME 04626	None	3/17/2006	Unplanned- complaint	Serious	1910.1001(j)(4)(i)	Asbestos/ Labeling. Warning labels shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. When a building owner or employer identifies previously installed ACM and/or PACM, labels or signs shall be affixed or posted so that employees will be notified of what materials contain ACM and/or PACM. The employer shall attach such labels in areas where they will clearly be noticed by employees who are likely to be exposed, such as at the entrance to mechanical room/areas. Signs required by paragraph (j)(3) of this section may be posted in lieu of labels so long as they contain information required for labelling.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	9/11/2006	\$7,000
NCTAMSLANT Det 175 Ridge Road Cutler, ME 04626	None	3/17/2006	Unplanned- complaint	Serious	1910.1001(k)(1)	Asbestos/ Housekeeping. All surfaces shall be maintained as free as practicable of ACM waste and debris and accompanying dust.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	10/9/2006	\$7,000
NCTAMSLANT Det 175 Ridge Road Cutler, ME 04626	None	3/17/2006	Unplanned- complaint	Serious	1910.1001(k)(2)	Asbestos/ Housekeeping. All spills and sudden releases of material containing asbestos shall be cleaned up as soon as possible.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	10/9/2006	\$7,000

OSHA Citations
 Serious Violations
 FY 2006

Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.37(a)(3)	Exit routes must be free and unobstructed. No materials or equipment may be placed, either permanently or temporarily, within the exit route. The exit access must not go through a room that can be locked, such as a bathroom, to reach an exit or exit discharge, nor may it lead into a dead-end corridor. Stairs or a ramp must be provided where the exit route is not substantially level.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/26/2006	\$7,000
Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.101(b)	Compressed gases. The in-plant handling, storage, and utilization of all compressed gases in cylinders, portable tanks, rail tankcars, or motor vehicle cargo tanks shall be in accordance with Compressed Gas Association Pamphlet P-1-1965.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/3/2006	\$7,000
Fleet & Industrial Supply 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.215(b)(9)	Abrasive wheels. Exposure adjustment. Safety guards, where the operator stands in front of the opening, shall be constructed so that the peripheral protecting member can be adjusted to the constantly decreasing diameter of the wheel. The maximum angular exposure above the horizontal plane of the wheel spindle shall never be exceeded, and the distance between the wheel periphery and the adjustable tongue or the end of the peripheral member at the top shall never exceed one-fourth inch.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/14/2006	\$7,000

OSHA Citations
Serious Violations
FY 2006

Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.219(e)(1)(i)	Machinery & guards. Where both runs of horizontal belts are seven (7) feet or less from the floor level, the guard shall extend to at least fifteen (15) inches above the belt or to a standard height, except that where both runs of a horizontal belt are 42 inches or less from the floor, the belt shall be fully enclosed in accordance with paragraphs (m) and (o) of this section.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/26/2006	\$7,000
Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.219(f)(3)	Sprockets and chains. All sprocket wheels and chains shall be enclosed unless they are more than seven (7) feet above the floor or platform. Where the drive extends over other machines or working areas, protection against falling shall be provided. This subparagraph does not apply to manually operated sprockets.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/26/2006	\$7,000
Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.303(b)(2)	Electrical equipment. Listed or labeled equipment shall be used or installed in accordance with any instructions included in the listing or labeling.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/27/2006	\$7,000
Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.304(e)(1)(iv)	Electrical. Overcurrent devices shall be readily accessible to each employee or authorized building management personnel. These overcurrent devices may not be located where they will be exposed to physical damage nor in the vicinity of easily ignitable material.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/26/2006	\$7,000

OSHA Citations
 Serious Violations
 FY 2006

Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.305(b)(2)	Electrical. All pull boxes, junction boxes, and fittings shall be provided with covers approved for the purpose. If metal covers are used they shall be grounded. In completed installations each outlet box shall have a cover, faceplate, or fixture canopy. Covers of outlet boxes having holes through which flexible cord pendants pass shall be provided with bushings designed for the purpose or shall have smooth, well-rounded surfaces.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/14/2006	\$7,000
Fleet & Industrial Supply, 467 W St, Bremerton, WA 98314	32416	4/10/2006	Planned	Serious	1910.305(j)(4)(ii)(E)	Electrical motors, motor circuits and controllers. The disconnecting means shall be readily accessible. If more than one disconnect is provided for the same equipment, only one need be readily accessible.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	6/13/2006	\$7,000
FISC, Fleet Industrial Supply, Bldg 7000, Silverdale, WA 98315	32416	4/10/2006	Planned	Serious	1910.305(g)(1)(iii)	Electrical, flexible cords & cables. Unless specifically permitted in paragraph (g)(1)(i) of this section, flexible cords and cables may not be used: As a substitute for the fixed wiring of a structure.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/26/2006	\$7,000
FISC, Fleet Industrial Supply, Bldg 7000, Silverdale, WA 98315	43137	7/10/2006	Planned	Serious	1910.22(b)(1)	Walking/working surfaces. Where mechanical handling equipment is used, sufficient safe clearances shall be allowed for aisles, at loading docks, through doorways and wherever turns or passage must be made. Aisles and passageways shall be kept clear and in good repairs, with no obstruction across or in aisles that could create a hazard.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/24/2006	\$7,000

OSHA Citations
Serious Violations
FY 2006

FISC, Fleet Industrial Supply, Bldg 7000, Silverdale, WA 98315	43137	7/10/2006	Planned	Serious	1910.37(d)(2)	Exit routes. During repairs or alterations, employees must not occupy a workplace unless the exit routes required by this subpart are available and existing fire protections are maintained, or until alternate fire protection is furnished that provides an equivalent level of safety.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/24/2006	\$7,000
FISC, Fleet Industrial Supply, Bldg 7000, Silverdale, WA 98315	43137	7/10/2006	Planned	Serious	1910.303(g)(1)(ii)	Electrical general requirements. Sufficient access and working space shall be provided and maintained about all electric equipment to permit ready and safe operation and maintenance of such equipment.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	7/24/2006	\$7,000
Military Sealift Command USNS San Jose (TAFS-7) Santa Rita, GU 96915	61755	9/4/2006	Unplanned Fatality Investigation	Serious	1910.67(c)(2)(v)	Powered Platforms, Manlifts, and Vehicle-Mounted Work Platforms. Employees shall always stand firmly on the floor of the basket, and shall not sit or climb on the edge of the basket or use planks, ladders, or other devices for a work position.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	10/27/2006	\$7,000
Military Sealift Command USNS San Jose (TAFS-7) Santa Rita, GU 96915	61755	9/4/2006	Unplanned Fatality Investigation	Serious	1910.67(c)(2)(i)	Powered Platforms, Manlifts, and Vehicle-Mounted Work Platforms. Lift controls shall be tested each day prior to use to determine that such controls are in safe working condition.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	10/25/2006	\$7,000

OSHA Citations
Serious Violations
FY 2006

Military Sealift Command USNS San Jose (TAFS-7) Santa Rita, GU 96915	61755	9/4/2006	Unplanned Fatality Investigation	Serious	1910.67(c)(2)(ii)	Powered Platforms, Manlifts, and Vehicle-Mounted Work Platforms. Only trained persons shall operate an aerial lift.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	10/25/2006	\$7,000
Naval Undersea Warfare Center 610 Dowell Street Bldg 105 Keyport, WA 98345	61015	9/13/2006	Planned	Serious	1910.1001(j)(2)(i)	Asbestos Communication. Building and facility owners shall determine the presence, location, and quantity of ACM and/or PACM at the work site. Employers and building and facility owners shall exercise due diligence in complying with these requirements to inform employers and employees about the presence and location of ACM and PACM.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	11/1/2006	\$7,000
Naval Undersea Warfare Center 610 Dowell Street, Bldg 105, Keyport, WA 98345	61015	9/13/2006	Planned	Serious	1910.1001(j)(4)(i)	Asbestos/ Labeling. Warning labels shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. When a building owner or employer identifies previously installed ACM and/or PACM, labels or signs shall be affixed or posted so that employees will be notified of what materials contain ACM and/or PACM. The employer shall attach such labels in areas where they will clearly be noticed by employees who are likely to be exposed, such as at the entrance to mechanical room/areas. Signs required by paragraph (j)(3) of this section may be posted in lieu of labels so long as they contain information required for labelling.	OPNAVINST 5100.23G Chapter 11. Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	10/2/2006	\$7,000