



How not to stop your speedboat

May, 1967 -- A 16-foot runabout pierced through the mid hull section of a 30-foot cabin cruiser in a collision on a lake in Missouri. One passenger in the cabin cruiser was killed, and eight were injured. Each boat carried five persons. The reported probable cause of this recreational accident was excessive speed and poor visibility.

What's really sad is that careless boating accidents like this still happen today.