

I yelled and tried to signal for help, but no one noticed my situation. The yellowshirt then began to taxi the aircraft with me still attached! In fear of being dragged across the flight deck, I quickly pulled myself free. However, that action resulted in the amputation of the last inch of my left ring finger.

A fellow Marine quickly rushed me to medical, and I subsequently was flown to Balboa Naval Medical Center. The next morning, I went into surgery where I received 22 stitches, an aluminum foil splint inside my finger, and a screw to re-attach the bone.

As a result of this incident, I learned two key lessons. First, communication always is a key function when operating in a crew environment. Without visual or verbal cues, chaos, complacency, and assumptions will occur. Lastly, **never** touch any moving parts of an aircraft, unless everyone knows you're doing it. I learned the hard way and now have a constant reminder of how a couple simple steps could have prevented a personal nightmare. ✨

LCpl. Fitzhugh works as a troubleshooter at VMFA-323.

Simple Brass Ring

By AD2(AW) Nicholas Rafanello

Written maintenance procedures are in place for a reason. No matter how many times you've done a job before or how rushed you are, the only way to be 100 percent sure a job is done right is to do it by the book. I learned this truth the hard way, while doing what I thought was just routine maintenance.

I was doing inspection turns on a P-3C Orion aircraft when the No. 4 propeller was found out of limits. Initial adjustments were in work when a bolt was found wedged between the propeller pump housing and the reduction gearbox (RGB). The bolt had worn an out-of-limits groove in the gearbox, requiring a pump housing and RGB change.

Although anxious to get started, my crew had to wait almost an entire shift while airframers replaced an anchor nut on a fire-warning element. By the time we were able to get to work, we only had three hours left in the shift. Even though the No. 4 engine and propeller are major components, they don't take long to install.

As the mid-check supervisor, I was convinced we had adequate time to replace both, and we did. The entire process went so smoothly that we even had enough time to do a good clean up and provide a detailed passdown to our day-check relief. I thought it was a job well done.

Feeling good about the work we had done, I headed home. It wasn't long before I received a phone call from my leading petty officer (LPO) with some unwelcomed news. While doing his final inspection of our turn-in engine, which was slated to go to the Aviation Intermediate Maintenance Depot later that day, he found the propeller-shaft brass ring still was installed. This important item should have been removed from the old engine and placed on the new one during installation. If that engine had been started without the ring, the results could have been catastrophic. My LPO explained he would do some more research and get back to me later in the day.

As expected, I received a call telling me the problem had been resolved, and I also found out my CDI qualification had been suspended. Considering what the results could have been, I was relieved to hear the problem was discovered before it was too late.

This experience re-emphasized the importance of by-the-book maintenance and never permitting a perceived deadline, even a self-imposed one, to influence the accuracy of your efforts. ✨

Petty Officer Rafanello works in the powerplants shop at VP-26.

