



Warped Warning

Recently, inspectors found this sign, which was required to be posted on the exhaust trunk of a Navy ship. An inventive Sailor super-glued a wire picture frame hanger to the back of the sign and hooked it on to the lagging. Perty smart, except for one thing...the sign was made of plastic. Physics lesson: Heat + Plastic = Melt.

While this most likely would not have lead to a mishap, the lesson is a good one and can be summed up using three words ... ***Think ahead, people!***

By the way...this sign was replaced by a sheet-metal, engraved sign.